GUJARAT TECHNOLOGICAL UNIVERSITY

BE - SEMESTER-III (New) EXAMINATION - WINTER 2015

3			Date:21/12/2015 Total Marks: 70	
Subject Name: Manufacturing Processes - I Time: 02:30pm to 05:00pm Instructions:				
	1. 2.	Attempt all questions. Make suitable assumptions wherever necessary. Figures to the right indicate full marks.		
			MARKS	
Q.1		Short Questions	14	
C	1	Define feed in the turning operation		
	2	What is provided in place of tailstock in Capstan lathe?		
	3	Why is quick return mechanism used in shaping machine?		
	4	Give names of any two types of milling cutters.		
	5	What is the function of steady rest?		
	6	What is dead centre?		
	7	For which operation is the lead screw used? What is the function of reamer?		
	8 9			
	10	What is a face plate? What is function of a Mandrel?		
	11			
	12 13	1 , 1		
	14	What is the material of bed in conventional machine tool?		
Q.2	(a)	Give classification of grinding machine.	03	
	(b)	Define a Basic Machine Tool and state the general requirements of	of 04	
		machine tools?		
	(c)	• • • • • • • • • • • • • • • • • • • •	el 07	
		the main parts. State functions of each part.		
	(a)	OR With neat sketch explain how stroke length can be set on a shape	er 07	
	(c)	having crank and slotted link mechanism?	71 U 7	
Q.3	(a)	_	03	
Q.o	(b)		04	
	(c)	<u> </u>	h 07	
		neat sketch the taper turning method that can be used for tape	er	
		turning long length job.		
		OR		
Q.3	(a)		03	
	(b)		04	
0.4	(c)		07	
Q.4	(a)	Derive the formula to estimate the machine time calculation for	or 03	

turning operation

	(b)	Why different spindle speeds are provided on an engine Lathe?	04
		Explain	
	(c)	Draw a neat sketch with label of following operation and indicate	07
		direction of cutting parameters on it. i) Reaming ii) boring iii)	
		Counter boring iv) Countersinking v) Spot facing vi) Tapping vii)	
		Trepanning.	
		OR	
Q.4	(a)	Explain the following terms.	03
		i) Glazing ii) Loading iii) Dressing	
	(b)	Explain Up milling with help of neat sketch,	04
	(c)	Explain gang drilling machine with a neat sketch. How does it	07
		differ from multiple spindle machine?	
Q.5	(a)	Explain Centerless grinding process to grind inside hollow pipes.	03
	(b)	Derive equation for calculating the taper angle by compound	04
		slide method on Lathe operation.	
	(c)	Why alignment test are required on machine tool? With a neat	07
		sketch explain any two alignment test.	
		OR	
Q.5	(a)	Differentiate between centre type and centre less grinding	03
		machines.	
	(b)	With help of neat sketch explain vertical boring machine	04
	(c)	Explain simple indexing and compound indexing for a milling	07
		machine	
